


Manual  
for  
Garden Shed Extension  
2,17x1,91x2,27m

















# ASSEMBLY INSTRUCTIONS


## Garden Shed Extension






2170X1910X2270mm

<p>T2</p>  <p>L : 2180mm</p>	<p>X2</p>		<p>T8</p>  <p>L : 1830mm</p>	<p>X1</p>	
<p>T3</p>  <p>L : 2120mm</p>	<p>X2</p>		<p>T9</p>  <p>L : 1860mm</p>	<p>X1</p>	
<p>T4</p>  <p>L : 2172mm</p>	<p>X1</p>		<p>T10</p> 	<p>X2</p>	
<p>T5</p>  <p>L : 2172mm</p>	<p>X1</p>		<p>T11</p>  <p>L : 80mm</p>	<p>X2</p>	
<p>T6</p>  <p>L : 1912mm</p>	<p>X1</p>		<p>T12</p> 	<p>X2</p>	
<p>T7</p> 	<p>X2</p>		<p>T13</p> 	<p>X2</p>	


T14		X2
T15		X4


T1	 L: 2120mm	X6
----	--	----





TH1	 M4X13	X63
-----	--	-----




TH2	 M6x12	X44
-----	--	-----



TH3	 M4X10	X16
-----	--	-----




TH4		X8
-----	---	----




TH5		X39
-----	---	-----





 M4X13	TH1	x8
	T2	x2
	T13	x2








 M6X12	TH2	x20
	T12	x2
	T14	x2








	T11	x2
 M6X12	TH2	x4



	T4	X1
 M6X12	TH2	x2






Fix it with the screw removed (step 8).








TH2 x4

M6X12








Fix it with the screw removed (step 8 ).









M6X12

TH2 x4



	T6	X1
 M6X12	TH2	x8











TH1 x4









T9 X1








 M4X13	<b>TH1</b>	<b>x8</b>
	<b>T7</b>	<b>x2</b>









 M4X13	TH1	x6		T3	x1
	T1	x1		TH5	x6



 M4X13	TH1	x6		TH5	x6
	T1	x1			




 M4X13	TH1 x27		TH5 x27
	T1 x4		T3 x1






TH1 x4



24







24




A24







 M4X10	TH3	X8
 T15	T15	X4






	TH3	X8
	T10	X2







TH4 X8



## Contact information

Austria



Belgium



Croatia



Denmark



Estonia



Finland



France



Germany



Ireland



Italy



Latvia



Lithuania



Nederland



Norway



Poland



Portugal



Spain



Sweden



Switzerland



UK

